

Inspection Photos

Location Name: SCHANK J-65N66W /35SENW

Location #: 336706



Photo #1

Schank J 35-06 (05-123-19202) Wellsite

No Emergency contact number posted



Photo #2

Schank J 35-20 (05-123-26252) Wellsite

No Emergency contact number posted

Trash – pipe sealant can



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SCHANK J-65N66W /35SENW

Location #: 336706



Photo #3

Schank J 35-21 (05-123-26443) Wellsite

No Emergency contact number posted



Photo #4

Schank # 2, J 35-06, 35-20, 35-21

Battery site



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: SCHANK J-65N66W /35SEnw
Location #: 336706



Photo #5
Schank # 2, J 35-06, 35-20, 35-21
Unused Automation controls



Photo #6
Schank # 2, J 35-06, 35-20, 35-21
Wood debris near ECD line

Inspection Photos

Location Name: SCHANK J-65N66W /35SENW

Location #: 336706



Photo #7

Schank # 2, J 35-06, 35-20, 35-21

Unused Gas meter runs

from prev. FIR



Colorado Oil & Gas Conservation Commission
40.35884, -104.75174, 1418.0m, 166°
2019/01/31 12:22:35 PM

Photo #8

Schank # 2, J 35-06, 35-20, 35-21

Unused Gas meter runs

Have been removed



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SCHANK J-65N66W /35SENW

Location #: 336706



Photo #9

Schank # 2, J 35-06, 35-20, 35-21

Damaged Stormwater BMPs

from prev. FIR



Photo #10

Schank # 2, J 35-06, 35-20, 35-21

Stormwater BMPs

Have been repaired with riprap



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources