

Location Name: Investment Equipment LLC – Colorado 1-10 (Rem #12431)

Inspection Date: 1/31/2019



Photo # - 1



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Investment Equipment LLC – Colorado 1-10 (Rem #12431)
Inspection Date: 1/31/2019



Photo # - 2

Small leak at the stuffing box, repair in order to prevent oil impacted soil



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Investment Equipment LLC – Colorado 1-10 (Rem #12431)

Inspection Date: 1/31/2019



Photo # - 3

Location Name: Investment Equipment LLC – Colorado 1-10 (Rem #12431)
Inspection Date: 1/31/2019



Photo # - 4

Location Name: Investment Equipment LLC – Colorado 1-10 (Rem #12431)
Inspection Date: 1/31/2019



Photo # - 5

Location Name: Investment Equipment LLC – Colorado 1-10 (Rem #12431)
Inspection Date: 1/31/2019



Photo # - 6

Location Name: Investment Equipment LLC – Colorado 1-10 (Rem #12431)
Inspection Date: 1/31/2019



Photo # - 7

Location Name: Investment Equipment LLC – Colorado 1-10 (Rem #12431)

Inspection Date: 1/31/2019



Photo # - 8

Historic oil impacted soil at crude tank loadout



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Investment Equipment LLC – Colorado 1-10 (Rem #12431)
Inspection Date: 1/31/2019



Photo # - 9



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Investment Equipment LLC – Colorado 1-10 (Rem #12431)
Inspection Date: 1/31/2019



Photo # - 10



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Investment Equipment LLC – Colorado 1-10 (Rem #12431)
Inspection Date: 1/31/2019



Photo # - 11

Former oil skim pit excavation viewed to the north



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Investment Equipment LLC – Colorado 1-10 (Rem #12431)
Inspection Date: 1/31/2019



Photo # - 12

Former oil skim pit excavation viewed to the north-northwest



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Investment Equipment LLC – Colorado 1-10 (Rem #12431)

Inspection Date: 1/31/2019



Photo # - 13

Former oil skim pit excavation viewed to the south-southeast



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Investment Equipment LLC – Colorado 1-10 (Rem #12431)
Inspection Date: 1/31/2019



Photo # - 14

Former oil skim pit excavation viewed to the south. Dark area near base of excavation has hydrocarbon odor.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Investment Equipment LLC – Colorado 1-10 (Rem #12431)
Inspection Date: 1/31/2019



Photo # - 15

Former oil skim pit excavation viewed to the south. Dark area near base of excavation has hydrocarbon odor.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Investment Equipment LLC – Colorado 1-10 (Rem #12431)
Inspection Date: 1/31/2019



Photo # - 16

Former production pit viewed to the south, former OSP excavation in the background



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources