

Inspection Photo (s)
Coloroso A3
API # 05-045-12744
Inspection # 689303269



Location Photo #1



Location Photo #2



Inspection Photo (s)
Coloroso A3
API # 05-045-12744
Inspection # 689303269



Location Photo #3, stained material near separator at blow down line.



Location Photo #4, stained material near separator at blow down line.