

Inspection Photos

Location Name: HSR-KNOX-65N67W /3SWSE

Location #: 330419



Photo #1

HSR-Knox 15-3 (05-123-19095) Wellsite

Shut-In | SI

Delinquent MIT



Photo #2

HSR-Knox 15-3 Battery

Shut-down

Inspection Photos

Location Name: HSR-KNOX-65N67W /3SWSE

Location #: 330419



Photo #3

HSR-Knox 15-3 Battery

Unused Equipment

Latrine

