

Inspection Photos
Location Name: Lind Tank Battery
Location ID: 418858



Photo 1 – Tank Battery



Photo 2 – Unused Sound Wall

Inspection Photos
Location Name: Lind Tank Battery
Location ID: 418858



Photo 3 – Trash around sound wall

Photo 4 – Unused Wellhead parts by tank berm

Inspection Photos
Location Name: Lind Tank Battery
Location ID: 418858



Photo 5 – Unused 1” riser