

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/18/2019

Submitted Date:

03/18/2019

Document Number:

696300022**FIELD INSPECTION FORM**
 Loc ID 418858 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426012	TANK BATTERY	AC	08/20/2010		-	LIND TANK BATTERY	AC

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused wellhead parts piled on pallet near tank berm see photo #4		
Corrective Action:	Comply with Rule 603.f .	Date:	06/21/2019
Type	UNUSED EQUIPMENT		
Comment:	Sound wall appears to be unused, see photo #2		
Corrective Action:	Comply with Rule 603.f .	Date:	06/21/2019
Type	UNUSED EQUIPMENT		
Comment:	Appears to be unused and unmarked 1" riser at sound wall. See photo #5		
Corrective Action:	Comply with rule 603.f	Date:	06/21/2019
Type	TRASH		
Comment:	Trash around sound wall near separators, see photo #		
Corrective Action:	Comply with Rule 603.f, see photo 3	Date:	06/21/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		

Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared berm with Condensate Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		40.514560,-104.848670
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 426012 Type: TANK API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment: AC

Corrective Action:

Date:

**COGCC Comments**

Comment

On 3/18/2019, I Erica Petrie performed an inspection of the Lind Tank battery (Location ID 418858) owned and operated by Great Western Oil & Gas.  
 While on inspection I observed the following issue(s)  
 Unused sound walls, see photo 2, Cite 603.f  
 Unused wellhead parts, see photo 4, Cite 603.f  
 Trash around sound wall, see photo #3 Cite 603.f  
 Unused 1" riser not marked, see photo #5, Cite 603.f  
 END.

User

petrie

Date

03/18/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300023	Tank Battery Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4766039">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4766039</a>