

Inspection Photos

API: 05-071-06404

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 3/20/2019

Inspection Photos



Photo 1. Facing toward the recontoured access road.

Inspection Photos



Photo 2. Facing north toward the location.

Inspection Photos



Photo 3. There is vegetation beginning to establish at the location.