

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2019

Submitted Date:

03/28/2019

Document Number:

685100748**FIELD INSPECTION FORM**
 Loc ID 458702 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458686	WELL	DG	01/25/2019		123-48445	BUDDY 7-14HZ	DG
458687	WELL	DG	01/19/2019		123-48446	BUDDY 7-6HZ	DG
458688	WELL	DG	01/19/2019		123-48447	BUDDY 7-7HZ	DG
458689	WELL	DG	01/22/2019		123-48448	BUDDY 7-10HZ	DG
458690	WELL	DG	01/21/2019		123-48449	BUDDY 7-9HZ	DG
458691	WELL	DG	01/15/2019		123-48450	BUDDY 7-1HZ	DG
458692	WELL	DG	01/26/2019		123-48451	BUDDY 7-15HZ	DG
458693	WELL	DG	01/24/2019		123-48452	BUDDY 7-13HZ	DG
458694	WELL	DG	01/23/2019		123-48453	BUDDY 7-12HZ	DG
458695	WELL	DG	01/16/2019		123-48454	BUDDY 7-2HZ	DG
458696	WELL	DG	01/17/2019		123-48455	BUDDY 7-4HZ	DG
458697	WELL	DG	01/16/2019		123-48456	BUDDY 7-3HZ	DG
458698	WELL	DG	01/18/2019		123-48457	BUDDY 7-5HZ	DG
458699	WELL	DG	01/20/2019		123-48458	BUDDY 7-8HZ	DG
458700	WELL	DG	01/26/2019		123-48459	BUDDY 7-16HZ	DG
458701	WELL	DG	01/23/2019		123-48460	BUDDY 7-11HZ	DG

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>458686</u>	Type: <u>WELL</u>	API Number: <u>123-48445</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>458687</u>	Type: <u>WELL</u>	API Number: <u>123-48446</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>458688</u>	Type: <u>WELL</u>	API Number: <u>123-48447</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>458689</u>	Type: <u>WELL</u>	API Number: <u>123-48448</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>458690</u>	Type: <u>WELL</u>	API Number: <u>123-48449</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>458691</u>	Type: <u>WELL</u>	API Number: <u>123-48450</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>458692</u>	Type: <u>WELL</u>	API Number: <u>123-48451</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>458693</u>	Type: <u>WELL</u>	API Number: <u>123-48452</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>458694</u>	Type: <u>WELL</u>	API Number: <u>123-48453</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>458695</u>	Type: <u>WELL</u>	API Number: <u>123-48454</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>458696</u>	Type: <u>WELL</u>	API Number: <u>123-48455</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>458697</u>	Type: <u>WELL</u>	API Number: <u>123-48456</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>458698</u>	Type: <u>WELL</u>	API Number: <u>123-48457</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>458699</u>	Type: <u>WELL</u>	API Number: <u>123-48458</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>458700</u>	Type: <u>WELL</u>	API Number: <u>123-48459</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>458701</u>	Type: <u>WELL</u>	API Number: <u>123-48460</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>

Well Drilling

Rig: Rig Name: Precision Drillin Rig # Pusher/Rig Manager: _____
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES
 Pressure Test BOP: Pass Test Pressure PSI: _____ Safety Plan: YES

Drill Fluids Management:

Lined Pit:	_____	Unlined Pit:	_____	Closed Loop:	YES	Semi-Closed Loop:	_____
Multi-Well:	YES	Disposal Location:	_____				
Comment:	<div></div>						
Corrective Action:	<div></div>					Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Slope Roughening	Pass					
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Ditches	Pass	Ditches	Pass			
Culverts	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. Continuing Education Inspection	medinaj	03/28/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100749	Loc Pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4777025