

Inspection Photos

Location Name: COLUMBINE SPRINGS FEDERAL 6-14-4-104

Location ID: 05-103-10063

Inspection: 679703541



Photo 1. Location looking west.



Photo 2. Tank without label or cover.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: COLUMBINE SPRINGS FEDERAL 6-14-4-104

Location ID: 05-103-10063

Inspection: 679703541



Photo 3. Container without label.



Photo 4. Container without label.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: COLUMBINE SPRINGS FEDERAL 6-14-4-104

Location ID: 05-103-10063

Inspection: 679703541



Photo 5. Oily waste on ground at pump jack.



Photo 6. Oily waste on ground next to tank.



Inspection Photos

Location Name: COLUMBINE SPRINGS FEDERAL 6-14-4-104

Location ID: 05-103-10063

Inspection: 679703541



Photo 7. Riser without cap.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources