

Inspection Photos

Location Name: COLTRANE-IGO-65N66W /28SENW

Location #: 323060



Photo #1

Coltrane-Igo # 1 (05-123-12504) Wellsite

Shut-In | LOTO

**No Orange SI / TA tag per agreement
from prior FIR**



Photo #2

Coltrane-Igo # 1 Wellsite

Shut-In | LOTO

Orange SI / TA tag NOT posted per agreement



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: COLTRANE-IGO-65N66W /28SENW

Location #: 323060



Photo #3

Coltrane-Igo # 1, Igo 28-3H6 Battery

Shut-down

**Contents / Capacity not posted on crude oil tank
from prior FIR**



Photo #4

Coltrane-Igo # 1, Igo 28-3H6 Battery

Shut-down

Contents / Capacity NOW posted on crude oil tank



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources