

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402019757
Date Received:
04/24/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:
6 of 6 CAs from the FIR responded to on this Form
6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Daniel Lapp	970-629-9525	dlapp@foundationenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 679703541
Inspection Date: 04/01/2019 FIR Submit Date: 04/01/2019 FIR Status:

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC Company Number: 10112
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 316229

Location Name: COLUMBINE SP FED-64S104W Number: 14NESW County: RIO BLANCO
Qtrqtr: NESW Sec: 14 Twp: 4S Range: 104W Meridian: 6
Latitude: 39.708820 Longitude: -109.042760

FACILITY - API Number: 05-103-00 Facility ID: 258306

Facility Name: COLUMBINE SP FED Number: 6-14-4-104
Qtrqtr: NESW Sec: 14 Twp: 4S Range: 104W Meridian: 6
Latitude: 39.708820 Longitude: -109.042760

CORRECTIVE ACTIIONS:

1 CA# 123746
Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e. Date: 05/01/2019

Response: CA COMPLETED Date of Completion: 04/15/2019

Operator Comment: Repair well head sign

COGCC Decision:

COGCC
Representative:

2 CA# 123747

Corrective Action: Install sign to comply with Rule 210.d.

Date: 06/03/2019

Response: CA COMPLETED

Date of Completion: 04/15/2019

Operator
Comment: Installed cover and 40 bbl label on fiberglass tank

COGCC Decision: _____

COGCC
Representative:

3 CA# 123748

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 05/01/2019

Response: CA COMPLETED

Date of Completion: 04/15/2019

Operator
Comment: Clea up oil stains around well head

COGCC Decision: _____

COGCC
Representative:

4 CA# 123749

Corrective Action: Install sign to comply with Rule 210.d.

Date: 06/03/2019

Response: CA COMPLETED

Date of Completion: 04/15/2019

Operator
Comment: remove and cap unused riser

COGCC Decision: _____

COGCC
Representative:

5 CA# 123750

Corrective Action: Install sign to comply with Rule 210.b.

Date: 06/03/2019

Response: CA COMPLETED

Date of Completion: 04/15/2019

Operator
Comment: Remove unlabeled oil day tank

COGCC Decision: _____

COGCC
Representative:

6 CA# 123751

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 05/01/2019

Response: CA COMPLETED

Date of Completion: 04/15/2019

Operator Comment: Clean up oil stains around blowdown tank

COGCC Decision:

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions resolved

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Alyssa Beard

Signed:

Title: HSE Manager

Date: 4/24/2019 12:44:32 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402019771	CSF 6-14 2
402019773	CSF 6-14 3
402019774	CSF 6-14 4
402019775	CSF 6-14 5
402019777	CSF 6-14 6
402019778	CSF 6-14 7
402019779	CSF 6-14

Total Attach: 7 Files