

Inspection Photos
Location Name: Elkhorn Company B#7
Location ID: 318599



Photo 1 Loc pic. Debris/weeds. Dead weeds around location.

Photo 2 Loc pic. Debris/weeds. Dead weeds around location.

Inspection Photos
Location Name: Elkhorn Company B#7
Location ID: 318599



Photo 3 WH sign

Photo 4 Debris/weeds: dead weeds around electric panel.

Inspection Photos
Location Name: Elkhorn Company B#7
Location ID: 318599



Photo 5 Stained soil around WH

Photo 6 Debris/weeds: dead weeds in PU

Inspection Photos
Location Name: Elkhorn Company B#7
Location ID: 318599



Photo 7 Debris/weeds: Dead weeds on location.

Photo 8 Debris/weeds: dead weeds on location