

Inspection Photos
Location Name: Carl R Deepe B#1
Location ID: 317861



Photo 1 Unused equipment: bare electric wires, electric panel's and guard.



Photo 2 WH sign installed from previous inspection.

Inspection Photos
Location Name: Carl R Deepe B#1
Location ID: 317861



Photo 3 Unused equipment: Cement base. Stained soil in middle of cement base.



Photo 4 Unused equipment: electric panel.

Inspection Photos
Location Name: Carl R Deepe B#1
Location ID: 317861



Photo 5 Unmarked unused and not LOTO riser. Trash electric line, spark plugs