

Inspection Photos

API: 05-055-06148

Operator: PETROGLYPH OPERATING CO

Inspection Date: 5/1/2019

Inspection Photos



Photo 1. Facing northeast toward the access road. Vegetation has not established along the road.

Inspection Photos



Photo 2. Facing northwest toward the location. Vegetation appears to be fully established.