

Inspection Photos
Location Name: Three Siblings A Pad
Location: 419140



Location at the Entry



Weeds on location pad surface

Inspection Photos
Location Name: Three Siblings A Pad
Location: 419140



Run on and sediment moving onto pad surface



Run off and sediment movement at fill slope