



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	May 2, 2019 8:17:26 AM MDT
Server Receive Date:	May 7, 2019 6:57:23 PM MDT
Reference Number:	20190502-18105217875
Location:	Unknown Location

Information

Name	celkins@gobrainstorm.net
Date	May 1, 2019
Well Name	OLGUIN GAS UNIT 32-6-18 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean Up Contaminated Soils Grading of Well Pad

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos

