

## Pit Status Evaluation Form

### Pit Overview:

<b>Pit Name:</b> MARY 1-17	<b>Facility ID:</b> 114844
<b>Current Status:</b> Unknown	<b>Status Date:</b> 9/23/1999
<b>Current Operator:</b> AMPET INC / 2550	
<b>Updated Operator:</b> MEYER OIL COMPANY - 57000	
<b>Form 15 Pit Permit Doc #:</b> NA	<b>Permit Date:</b> NA
<b>Related Facilities:</b> API # 05-013-06203 (Facility ID 206708), Location 379785	

<b>County:</b> Boulder			
<b>Township:</b> 2N	<b>Range:</b> 69W	<b>Section:</b> 17	<b>QQ:</b> CSW
<b>Original Latitude/ Longitude:</b> 40.134316 / -105.145061			
<b>Updated Latitude/ Longitude:</b> /			
<b>Basis for Location Change:</b>			

### Pit Inspection/Information Request:

<b>Field Inspection Date:</b>	<b>Document #:</b>
<b>Pit Still Present in Field:</b> No	
<b>Visible Surface Impacts:</b> <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
<b>Inspection Notes:</b>	
<b>Operator Required to Submit Form:</b> NA	<b>Due Date:</b>
<b>Form Request Sent To:</b>	<b>Sent Date:</b>

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                  |
|-------------------------------------|---|------------------|
| <input type="checkbox"/>            | Form 15 Pit Permit – Doc #: NA              | Date: NA         |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 580923         | Date: 7/17/1987  |
|                                     | Doc #: 500137312                            | Date: 10/05/1994 |
|                                     | Doc #:                                      | Date:            |
| <input type="checkbox"/>            | Form 27 Remediation Workplan – Project #:   | Date:            |
| <input type="checkbox"/>            | Form 4 Sundry Notice – Doc #:               | Date:            |
| <input type="checkbox"/>            | COGIS Document – Doc #:                     | Date:            |
| <input type="checkbox"/>            | Pit Inventory – Doc #:                      | Date:            |
| <input type="checkbox"/>            | Duplicate Record – Duplicate Pit(s) #:      |                  |
| <input type="checkbox"/>            | Aerial Photo Verification (photos attached) |                  |
| <input type="checkbox"/>            | Other:                                      |                  |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date:**

#### Timing of Pit Closure:

Well PA 1/18/1994, Passed PA inspection 10/05/1994

#### Pit Status Review Summary:

Based on records review, there is no evidence that there was a pit on location. Inspection reports document a concrete water vault on location. Inspections note spill associated with concrete water vault removal. Later inspections note site was restored; TB area now developed. Well passed final reclamation inspection 10/05/1994. Pit status changed to closed.