

# *Inspection Photos*

*Loc#442832*

*Operator: Ursa*

*Inspection Number: 692400983*

*Inspection Date: 5/17/19*





Photo#1:  
Overview of Location to Northwest.

May 17, ,2019




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa Monument Ridge B Pad Loc#442832



Photo#2:  
Establishment of Cheat grass, Tumble mustard, and  
Filaree.

May 17, ,2019



Photo#3:  
Establishment of Cheat grass, Tumble mustard, and  
Filaree.



Photo#4:  
BMPs on access road need maintenance



Photo#5:  
BMPs on access road need maintenance

May 17, ,2019



**Photo#6:**  
Washed out BMP at North end of site.

May 17, ,2019



**Photo#7:**  
Washed out BMP at North end of site.



Photo#8:  
Cut slope needs to be stabilized.

May 17, ,2019



Photo#9:  
View over east Well line up; no wildlife escape boards installed.



Photo#8:  
Evidence of sediment migration.

May 17, ,2019



Photo#9:  
Debris weeds blown into equipment.