

Inspection Photos
Location Name: Cogburn 1-1
Location ID: 05-009-06551



1. Meter run and Vertical gas separator



2. Gas meter has been removed

Inspection Photos
Location Name: Cogburn 1-1
Location ID: 05-009-06551



3. Location and access