

Inspection Photos
Location Name: Great Western 23-44
Location ID: 333057



Photo 1: Wellhead; unused equipment, No Emergency Contact #.