

Inspection Photos

Operator: Maralex Resources
Location/API #: 067-06537
Date: 5-13-2019



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward.



Photo 3. View of reference area vegetation north of the project area.



Photo 4. View of kochia (*Kochia scoparia*) debris and seedlings within the project area.