

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402052801

Date Received:  
05/22/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Jacob Evans

970-304-5329

jacob.evans@nbleenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697300068

Inspection Date: 05/13/2019

FIR Submit Date: 05/14/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 446700

Location Name: MACBAIN Number: 1 County: \_\_\_\_\_

Qtrqtr: NWNE Sec: 32 Twp: 5N Range: 65W Meridian: 6

Latitude: 40.362857 Longitude: -104.680518

FACILITY - API Number: 05-123-00 Facility ID: 449494

Facility Name: McBain Number: 1

Qtrqtr: NWNE Sec: 32 Twp: 5N Range: 65W Meridian: 6

Latitude: 40.362857 Longitude: -104.680518

CORRECTIVE ACTIONS:

1 CA# 125179

Corrective Action: Backfill or secure potholes to protect livestock.

Date: 05/24/2019

Response: CA COMPLETED

Date of Completion: 05/23/2019

Operator Comment: potholes will be filled by EOD of 5/23/2019

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 125180

Corrective Action: Comply with Rule 603.f .

Date: 05/24/2019

Response: CA COMPLETED

Date of Completion: 05/17/2019

Operator  
Comment: monitoring well materials have been removed

COGCC Decision:

COGCC  
Representative:

3 CA# 125181

Corrective Action: Cap wells within 10 day. Maintain, protect, or replace wells within 45 days. If livestock damage continues to be a problem additional protection or recompletion to flush mount may be required.

Date: 05/24/2019

Response: CA COMPLETED

Date of Completion: 05/17/2019

Operator  
Comment: wells have been capped

COGCC Decision:

COGCC  
Representative:

4 CA# 125182

Corrective Action: Comply with 1004 Rules

Date: 06/28/2019

Response: CA COMPLETED

Date of Completion: 06/28/2019

Operator  
Comment: Location will be contoured and graded to match pre-existing conditions and comply with COGG 1004 Rules. Meter house is not Noble Energy Equipment, it is DCP's.

COGCC Decision:

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jacob Evans

Signed:

Title: Environmental Coordinator

Date: 5/22/2019 3:55:43 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files