

Inspection Photos
Location Name: WALKER 42-19
API#: 05-071-06858
INSP. #: 695100816



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN



Inspection Photos
Location Name: WALKER 42-19
API#: 05-071-06858
INSP. #: 695100816



PHOTO 3: UNUSED EQUIPMENT STORED ON LOCATION.
REMOVED UNUSED EQUIPMENT TO COMPLY WITH 603.f. CA
DATE 7/6/19.