

**Inspection Photos**  
**Location Name: Hebron 01-18HR**  
**Location ID: 414127**



**Photo 1. Unlabeled tank with no apparent berm or liner.**



**Photo 2. Stained soil and free product at pump jack.**



**Inspection Photos**  
**Location Name: Hebron 01-18HR**  
**Location ID: 414127**



**Photo 3. Mixed soil and gravel with debris and stained soil.**



**Photo 4. Close-up of photo 3.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Hebron 01-18HR**  
**Location ID: 414127**



**Photo 5. Example of stained soil on location.**



**Photo 6. Example of stained soil on location.**





**Inspection Photos**  
**Location Name: Hebron 01-18HR**  
**Location ID: 414127**



**Photo 7. Stained soil and free product at pump jack.**



**Photo 8. 2 risers not LOTO or marked for abandonment.**

**Inspection Photos**  
**Location Name: Hebron 01-18HR**  
**Location ID: 414127**



**Photo 9. Example of stained soil on location.**



**Photo 10. Equipment stored on location.**

