

**Inspection Photos**  
**Location Name: Ochsner 50-441 Battery**  
**Location ID: 430370**



**Photo 1: Location**



**Photo 2: Debris removed, Refer to DOC#: 679600853**

Inspection Photos  
Location Name: Ochsner 50-441 Battery  
Location ID: 430370



Photo 3: Debris removed; Refer to DOC#: 679600835



Photo 4: Majority of debris removed; Refer to DOC#: 679600835

Inspection Photos  
Location Name: Ochsner 50-441 Battery  
Location ID: 430370



**Photo 5: Unused equipment removed; Refer to DOC#:  
679600835**



**Photo 6: Debris (south of separator) next to access road.**

**Inspection Photos**  
**Location Name: Ochsner 50-441 Battery**  
**Location ID: 430370**



**Photo 7: Remaining Debris**



**Photo 8: Remaining Debris**