

Inspection Photos

Location Name: Horsetail 07H Location ID 442408

Inspection Date: 8/13/2019



Photo 1 – Stockpile 1 of 2 of impacted material from Horsetail 7CPB spills in bermed lined containment. Free oil present.



Photo 2 – Stockpile 2 of 2 of impacted material from Horsetail 7CPB spills in bermed lined containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources