

Inspection Photos

API: 071-08462

API: 071-08970

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/20/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08462 | Date: 8/20/2019

Inspection Photos



Photo 1. Facing west at the beginning of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08462 | Date: 8/20/2019

Inspection Photos



Photo 2. Facing northwest along the access road. Vegetation is well established along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08462 | Date: 8/20/2019

Inspection Photos



Photo 3. There is an erosion channel along the road.



Photo 4. The erosion channel leads to the culvert which is partially filled in..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08462 | Date: 8/20/2019

Inspection Photos



Photo 5. Facing northwest along the access road. Vegetation is well established along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08462 | Date: 8/20/2019

Inspection Photos



Photo 6. Facing north toward the location. Perennial vegetation is well established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08462 | Date: 8/20/2019

Inspection Photos



Photo 7. Facing south toward the location. Perennial vegetation is well established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08462 | Date: 8/20/2019

Inspection Photos



Photo 8. Facing east toward the location. Perennial vegetation is well established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08462 | Date: 8/20/2019