

Inspection Photos

API: 071-08611

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/20/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08611 | Date: 8/20/2019

Inspection Photos



Photo 1. Facing northeast at the beginning of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08611 | Date: 8/20/2019

Inspection Photos



Photo 2. Facing northeast along the access road. Vegetation is well established along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08611 | Date: 8/20/2019

Inspection Photos



Photo 3. Facing northwest toward the location. Vegetation is well established along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08611 | Date: 8/20/2019

Inspection Photos



Photo 4. Facing north toward the fill slope. Perennial vegetation is well established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08611 | Date: 8/20/2019

Inspection Photos



Photo 5. Facing southwest toward the location. Perennial vegetation is well established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08611 | Date: 8/20/2019

Inspection Photos



Photo 6. There is an area at the center of the location which has noxious weeds (Common mullein).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08611 | Date: 8/20/2019