

Inspection Photos

API: 071-07930

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/21/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07930 | Date: 8/21/2019

Inspection Photos



Photo 1. Facing east along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07930 | Date: 8/21/2019

Inspection Photos



Photo 2. There is an area of erosion along the access road near the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07930 | Date: 8/21/2019

Inspection Photos



Photo 3. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07930 | Date: 8/21/2019

Inspection Photos



Photo 4. There is a short cross fence at the location which needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07930 | Date: 8/21/2019

Inspection Photos



Photo 5. There is an area at the east side of the location which has noxious weeds (Canada thistle).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07930 | Date: 8/21/2019

Inspection Photos



Photo 6. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07930 | Date: 8/21/2019