

Inspection Photos

API: 071-09619

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/21/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09619 | Date: 8/21/2019

Inspection Photos



Photo 1. Facing east along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09619 | Date: 8/21/2019

Inspection Photos



Photo 2. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09619 | Date: 8/21/2019

Inspection Photos



Photo 3. Well is temp abandoned. Well sign needs to be updated and securely fastened.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09619 | Date: 8/21/2019

Inspection Photos



Photo 4. There is an area at the center of the location which has noxious weeds (Canada thistle).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09619 | Date: 8/21/2019