

Inspection Photos

API: 071-07693

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/21/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07693 | Date: 8/21/2019

Inspection Photos



Photo 1. There is signs of erosion along the main road near the Led 31-21 location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos



Photo 2. There is erosion issues along the access road to the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Well sign is updated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07693 | Date: 8/21/2019