

Inspection Photos
Location Name: Luchini Water Disposal Well #1
API: 05-007-05179



Luchini 32-6-12 #1 location photo.



Stained and wet well head at the Luchini 32-6-12 #1.

Inspection Photos
Location Name: Luchini Water Disposal Well #1
API: 05-007-05179



Spill/Release Point ID #466711 point source.



Standing water at Spill/Release Point ID #466711.

Inspection Photos
Location Name: Luchini Water Disposal Well #1
API: 05-007-05179



Top seam of PBV appears to be damaged. PBV is rusty and requires painting and labeling per Rule 210.d.



Luchini Water Disposal Well #1 with well house removed.