

Inspection Photos
Location Name: Dill Gulch 1-17
Location ID: 316744



Photo 1. Stained soil at wellhead.



Photo 2. Stained soil and debris at wellhead.



Inspection Photos
Location Name: Dill Gulch 1-17
Location ID: 316744



Photo 3. Stained soil on location between wellhead and tank battery.



Photo 4. Stained soil and debris at pump jack.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dill Gulch 1-17
Location ID: 316744



Photo 5. Stained soil at tank loadout valve.



Photo 6. Stained soil and debris in tank battery.

Inspection Photos
Location Name: Dill Gulch 1-17
Location ID: 316744



Photo 7. Stained soil and debris in tank battery.



Photo 8. Stained soil and debris in tank battery.



Inspection Photos
Location Name: Dill Gulch 1-17
Location ID: 316744



Photo 9. Stained soil and debris in tank battery.



Photo 10. Stained soil and debris in tank battery.



Inspection Photos
Location Name: Dill Gulch 1-17
Location ID: 316744



Photo 11. Stained soil at tank loadout valve.



Photo 12. Stained soil in tank battery.



Inspection Photos
Location Name: Dill Gulch 1-17
Location ID: 316744



Photo 13. Incomplete battery sign.



Photo 14. Houndstongue on location.

