

Inspection Photos
Location Name: Gnat Hill 1-29
Location ID: 425278



Photo 1. Overview of location facing southeast.



Photo 2. Wellhead sign knocked over.



Inspection Photos
Location Name: Gnat Hill 1-29
Location ID: 425278



Photo 3. Stained soil and debris at wellhead.



Photo 4. Close-up of photo 3.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources