

Inspection Photos
Location Name: Buck Peak 34-23 HD
Location ID: 313019



Photo 1. Overview of location facing west.



Photo 2. Houndstongue on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Buck Peak 34-23HD
Location ID: 313019



Photo 3. Access road overgrown.

