

Inspection Photos
Location Name: Voloshin 3-25
Location ID: 432878



Photo 1. Noxious weeds on location.



Photo 2. Houndstongue on location.

Inspection Photos
Location Name: Voloshin 3-25
Location ID: 432878



Photo 3. Stained soil at wellhead.



Photo 4. Trash at wellhead.