

Inspection Photos

API#103-06230

Operator: Chevron

Inspection Number: 692401238

Inspection Date: 8/2/19





Photo#1:
Remnants of Concrete Pad & Debris on Location.

August 2, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron PA Union Pacific API#103-06230



Photo#2:
Remnants of Concrete Pad & Debris on Location.



Photo#3:
Remnants of Concrete Pad & Debris on Location

August 2, 2019