

Photo#1:

View North over Location Center



Photo#2:

View South over Location Center



February 15,2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron PA Union Pacific API#103-06230

Photo#3:

Remnants of Concrete Pad & Debris on Location.



Photo#4:



February 15, 2017