

Kirby Eidson 28-4
API: 05-103-08974
Inspection: 679708174



Photo 1. Location.

Kirby Eidson 28-4
API: 05-103-08974
Inspection: 679708174



Gas leak

Photo 2. Separator.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Kirby Eidson 28-4
API: 05-103-08974
Inspection: 679708174



Photo 3. Separator gas leak.

Kirby Eidson 28-4
API: 05-103-08974
Inspection: 679708174



Gas leak

Photo 4. Separator gas leak.

Kirby Eidson 28-4
API: 05-103-08974
Inspection: 679704407



Photo 5. Gas leak at separator on 7-18-2019.