

Inspection Photos

API#103-08919

Operator: Eagle Operating

Inspection Number: 692401265

Inspection Date: 8/2/19



Photo#1:
Shallow pit remains on Location.

August 2, 2019



Photo#2:
Material piles remain on Location.

August 2, 2019



Photo#3:
Anchors remain on Location.



Photo#4:
Access road has not been reclaimed.

August 2, 2019



Photo#5:
Access road has not been reclaimed.



Photo#6:
Site has not been reclaimed.

August 2, 2019