Inspection Photos

Location Name: ROTHE-65N63W /31SWSW

Location #: 306070





Photo #1

Rothe CSW-31 (05-123-23945) Wellsite

Temporarily Abandoned | TA

Weeds

Photo #2
Rothe #1, 13-31, CSW-31 Battery
Shut-down | Inactive

