

## Pit Status Evaluation Form

### Pit Overview:

<b>Pit Name:</b> ABNER GUTHRIE 2 & 3	<b>Facility ID:</b> 113811
<b>Current Status:</b> Unknown	<b>Status Date:</b> 9/23/1999
<b>Current Operator:</b> CLARK ENERGY CORP / 17530	
<b>Updated Operator:</b> PETROSHARE CORPORATION	
<b>Form 15 Pit Permit Doc #:</b> 698263	<b>Permit Date:</b> 8/15/1973
<b>Related Facilities:</b> Location ID 319681	

<b>County:</b> Adams			
<b>Township:</b> 1S	<b>Range:</b> 67W	<b>Section:</b> 2	<b>QQ:</b> SWNE
<b>Original Latitude/ Longitude:</b> 39.995089 / -104.854141			
<b>Updated Latitude/ Longitude:</b> /			
<b>Basis for Location Change:</b>			

### Pit Inspection/Information Request:

<b>Field Inspection Date:</b> 9/19/2019	<b>Document #:</b> 689501000
<b>Pit Still Present in Field:</b> No	
<b>Visible Surface Impacts:</b> <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
<b>Inspection Notes:</b>	
Inspection found no surface indication of a pit present in the location.	
<b>Operator Required to Submit Form:</b> NA	<b>Due Date:</b>
<b>Form Request Sent To:</b>	<b>Sent Date:</b>

## Pit Status Evaluation:

### Pit Status Review Documents:

- |   |                 |
|---|-----------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 698263          | Date: 8/15/1973 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 698266         | Date: 4/2/1985  |
| Doc #: 698264   | Date: 2/6/1990  |
| Doc #:  | Date:           |
| <input type="checkbox"/> Form 27 Remediation Workplan – Project #:              | Date:           |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #:                          | Date:           |
| <input type="checkbox"/> COGIS Document – Doc #:                                | Date:           |
| <input type="checkbox"/> Pit Inventory – Doc #:                                 | Date:           |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #:                 |                 |
| <input checked="" type="checkbox"/> Aerial Photo Verification (photos attached) |                 |
| <input type="checkbox"/> Other:   |                 |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date:**

Timing of Pit Closure:

### Pit Status Review Summary:

Field inspection (doc #689501000) found no surface indication of a pit on location. Records review and aerial photos found document that any pits on location were closed prior to 1985 inspections. Pit status has been changed to closed.