

Inspection Photos
Location Name: Dwinell 1
Location ID: 324591



Photo 1. Pit.



Photo 2. Debris on location.



Inspection Photos
Location Name: Dwinell 1
Location ID: 324591



Photo 3. Debris on location.



Photo 4. Free fluid and stained soil in separator building.



Inspection Photos
Location Name: Dwinell 1
Location ID: 324591



Photo 5. Soil staining outside of housing for injection pump.



Photo 6. Free fluid and stained soil in pump building.



Inspection Photos
Location Name: Dwinell 1
Location ID: 324591



Photo 7. Free fluid and stained soil in pump building.



Photo 8. Free fluid and stained soil in pump building.

Inspection Photos
Location Name: Dwinell 1
Location ID: 324591



Photo 9. Berm does not appear compacted.



Photo 10. Swale area to west of tank battery.

