

Inspection Photos
Location Name: East Platte 1-1H
Location ID: 424175



Photo 1 – Pumping Unit



Photo 2 – Tank Battery

Inspection Photos
Location Name: East Platte 1-1H
Location ID: 424175



Photo 3 – Middle Tank – Content and NFPA Label

Photo 4 – Middle Tank – Content and NFPA Label

Inspection Photos
Location Name: East Platte 1-1H
Location ID: 424175



Photo 5 – Unmarked 2” Riser at Wellhead




Photo 6 – Unmarked 4” Riser West of ECD