

Pit Status Evaluation Form

Pit Overview:

Pit Name: SHANNON 1-14	Facility ID: 114365
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: EXTRACTION OIL & GAS INC / 10459	
Updated Operator:	
Form 15 Pit Permit Doc #:	Permit Date:
Related Facilities: SHANNON #MD 14-5 (API 05-001-08842) *well name change ~1996	

County: ADAMS			
Township: 1S	Range: 68W	Section: 14	QQ: NWNW
Original Latitude/ Longitude: 39.970269 / -104.975944			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts:	<input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|-----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 583061 | Date: 5/29/1990 |
| | Doc #: 341217 | Date: 1/20/1997 |
| | Doc #: 200051474 | Date: 3/16/2004 |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2223762 | Date: 1/29/1998 |
| <input checked="" type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: 114367 | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

No evidence of a pit on location.

Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location. Pit inventory and inspection reports document a cement vault on location. Pit status has been changed to Closed.

