


**Inspection Photos**  
**Location Name: DF Ranch 8-15**  
**Location ID: 310707**



**Photo 1 – Pumping Unit**



**Photo 2 – Stained Soil at Wellhead**

Inspection Photos  
Location Name: DF Ranch 8-15  
Location ID: 310707



Photo 3 – Stained Soil at Wellhead

Photo 4 – Stained Soil at Exhaust

**Inspection Photos**  
**Location Name: DF Ranch 8-15**  
**Location ID: 310707**



**Photo 3 – Stained Soil at Gas Engine**