

Inspection Photos
Location Name: BIBER 44-21 V
API#: 05-071-07243
INSP. #: 695101759



PHOTO 1: LOCATION

Inspection Photos
Location Name: BIBER 44-21 V
API#: 05-071-07243
INSP. #: 695101758



**PHOTO 3: UNUSED RISER. REMOVE RISER OR PUT BACK IN
USE AS PER NTO AND RULE 603.f. CA DATE 02-12-19**



PHOTO 2: WELL SIGN