

Inspection Photos
Location Name: Ruff 8-714
API ID: 123-18372



Photo #1 Wellhead, No Well or Emergency contact information. On 10/2/19



Photo #2 Wellhead, No Well or Emergency contact information. On 11/19/19

Inspection Photos
Location Name: Ruff 8-714
API ID: 123-18372



Photo #3 Variance Tag