

Inspection Photos
Location Name: Dow /23-28 Pad
Location #: 331380



Photo #1
DOW 23-28 (05-123-20593) Wellsite
Plugged & Abandoned | PA
~ 15 yds.
Appears to be cut & capped
Reclamation progressing



Photo #2
DOW 23-28 Battery
Abandoned | Most equipment removed
Reclamation progressing
Unused Automation controls & tower