

Inspection Photos

Location Name: 596-31A-65S96W 31NWNW Pad

Location ID: #335875

Inspection Date: November 14, 2019



Photo #1 – Facility sign.



Photo #2 – Corrected well signs (1).



Inspection Photos
Location Name: 596-31A-65S96W 31NWNW Pad
Location ID: #335875
Inspection Date: November 14, 2019



Photo #3 - Corrected well signs (2).

Photo #4 - Corrected well signs (3).



Inspection Photos

Location Name: 596-31A-65S96W 31NWNNE Pad

Location ID: #335875

Inspection Date: November 14, 2019



Photo #5 - Corrected well signs (4).



Photo #6 - Corrected well signs (5).



Inspection Photos
Location Name: 596-31A-65S96W 31NWNE Pad
Location ID: #335875
Inspection Date: November 14, 2019



Photo #7 - Corrected well signs (6).

Photo #8 - Corrected well signs (7).



Inspection Photos
Location Name: 596-31A-65S96W 31NWNE Pad
Location ID: #335875
Inspection Date: November 14, 2019



Photo #9 - Corrected well signs (8).



Photo #10 – Active fluids transport operations during inspection precluded tank battery inspection.

